

ABSTRACT

Surface treating methods of a titanium part may include the steps of determining an effective thickness of a hard oxide film to be formed on a surface of the titanium part, determining an effective surface roughness of the hard oxide film, and oxidation treating the surface of the titanium part under a desired treating temperature and a desired treating time such that both of the determined effective thickness and effective surface roughness are satisfied.